


SBB – Collision at Rafz – Two Views of North East End of Station



Could 'read through' to next visible signal (seen showing green above & red or yellow below) on right hand side have contributed to the mistake of the driver reading the incorrect signal on the right hand side of the platform track at the station?

